OR 23566-6 MAR 08 2010

54152

FEB 19 2010 NEW
DATE REVIEWER

Interlux®

BOTTOMKOTE® *PRO*

Dependable seasonal antifouling protection
Ablative action minimizes paint build up
High solid and reduced solvent emissions

KEEP OUT OF REACH OF CHILDREN
WARNING
See Side Panel for Additional Precautionary Statements

ONE U.S. GALLON
(3.785 L)

Y49

RED • ROJO

ACTIVE INGREDIENT	
CUPROUS OXIDE	25.00%
INERT INGREDIENTS	75.00%
	100.00%

COPPER AS METALLIC 22.20%
CONTAINS PETROLEUM DISTILLATES

EPA ESTABLISHMENT NO. 2693-NJ-1

EPA REGISTRATION NO. 23566-6

yachtpaint.com

BOTTOMKOTE® PRO

PRODUCT DESCRIPTION: Proven performance for boatyards that requires economical dependable seasonal antifouling protection. Ablative action minimizes paint build up and high solid, low VOC content reduces solvent emissions. Bottomkote Pro can be applied over all types of properly prepared bottom paints and surfaces except aluminum.
DIRECTIONS FOR USE: It is a violation of Federal law to use this product in a manner inconsistent with its labeling.
COMPATIBILITY: **Bottomkote Pro** can be applied over most other antifouling paints provided the old coating is tightly adhered, is in sound condition and has been thoroughly sanded with 80 grit wet-or-dry sandpaper. **Bottomkote Pro** can be applied by brush, roller or spray.

V.O.C.: Less than 330 grams/liter (2.75 lbs./gallon).
THINNER: Interlux Special Thinner 216 or Interlux Brush Ease 433.
CLEAN-UP: Special Thinner 216 or Brush-Ease 433.
THEORETICAL COVERAGE: 375 sq. ft./ gallon yields 2 mils dry film thickness.
THINNING: Thin only when necessary Do not exceed 10% maximum.
APPLICATION TEMPERATURE: 50°F (10°C)* and above (air and hull).

ESTIMATED DRY TIMES:

Temperature °F (°C)	Touch Dry	Overcoating Time Minimum	Immersion Time	
			Minimum	Maximum
50°F (10°C)	3 Hours	16 Hours	16 Hours	60 Days
73°F (24°C)	2 Hours	12 Hours	16 Hours	60 Days
95°F (35°C)	1 Hour	8 Hours	16 Hours	60 Days

*If the air temperature falls below 50°F (10°C) during the 16 hour dry time, extend the dry time and launch time to 36 hours.

PREPARATION

PREVIOUSLY PAINTED SURFACES - GOOD CONDITION:
Remove all traces of loose paint and contamination by sanding the entire surface with 80 grit wet-or-dry sandpaper; wipe surface clean with Special Thinner 216. Apply 2 coats of **Bottomkote Pro.**
PREVIOUSLY PAINTED SURFACES - POOR CONDITION:
Completely remove all old antifouling paint, using Interlux Interstrip 299E for fiberglass, and wood, and by sandblasting or grinding to near white metal for steel. Follow application systems below.
BARE FIBERGLASS:
It is very important that bare fiberglass be properly prepared to prevent delamination of the antifouling paint. Remove mold release wax using one of the following Interlux products. Fiberglass Surface Prep YMA601 or Fiberglass Solvent Wash 202 following the product label instructions. Fill any surface imperfections with Interlux Watertite YAV135 following the label instructions. After the surface has been properly cleaned, proceed with one of the application systems below.

APPLICATION SYSTEMS

BARE FIBERGLASS - NO SAND SYSTEM:
Clean the surface following the preparation procedure above. Apply one coat, of Interlux InterProtect/Æ 2000 or Fiberglass No-Sand Primer YPA200 following the label instructions for applying the primer and overcoating with antifouling paint. Apply two coats of **Bottomkote Pro,** allowing for the appropriate dry times.
BARE FIBERGLASS - SANDING SYSTEM:
Clean the surface following the preparation procedure above for bare fiberglass. Sand the entire surface with 80-grit sandpaper until a flat matte finish is obtained. Wipe the sanding residue off the surface with Fiberglass Solvent Wash 202. Sand and wipe clean. Apply two coats of **Bottomkote Pro** allowing for appropriate dry times.
BARE FIBERGLASS - BLISTER PREVENTION SYSTEM:
Apply the InterProtect system for the prevention of blisters. Contact the Interlux Technical Service Department at 1-800-468-7589 or visiting yachtpaint.com for complete instructions on the application of the InterProtect system.
BARE WOOD:
Sand the entire surface with 80-grit sandpaper. Wipe the sanding residue off the surface with Special Thinner 216. Apply the first coat of **Bottomkote Pro** thinned 10% with Special Thinner 216 or Brush-Ease 433. Fill seams with Interlux Seam Compound 30 (if necessary). Apply two more coats of **Bottomkote Pro** unthinned, allowing for the appropriate dry times.
UNDERWATER METALS:
Contact the Interlux Technical Service Department at 1-800-468-7589 for full information on how to properly prime underwater metals. DO NOT USE ON ALUMINUM.

Color difference may occur between actual paint and color swatch on front of can.

®, 'Fiberglass Bottomkote®', 'InterProtect®' and 'Interlux®' are registered trademarks of Akzo Nobel.

Interlux.
International Paint LLC.
2270 Morris Ave., Union, NJ 07083 • 908-686-1300

AKZO NOBEL

PRECAUTIONARY STATEMENTS
HAZARDS TO HUMANS AND DOMESTIC ANIMALS
WARNING

Causes eye irritation. Harmful if absorbed through skin. Avoid contact with skin, eyes, or clothing. Wear protective clothing such as gloves, long-sleeved cotton shirt, long pants, and hat. May be fatal if swallowed or inhaled. Do not breathe dust, vapor or spray mist. While spraying paint or sanding or sand blasting boat surfaces, wear a mask or a respirator jointly approved by the Mining Enforcement and Safety Administration and the National Institute for Occupational Safety and Health. Remove contaminated clothing and wash before reuse. Wash thoroughly with soap and water after handling.

FIRST AID

If swallowed:
- Immediately call a poison control center or doctor.
- Do not induce vomiting unless told to do so by a poison control center or doctor.
- Do not give any liquid to the person.
- Do not give anything by mouth to an unconscious person.

If on skin or clothing:
- Take off contaminated clothing.
- Rinse skin immediately with plenty of water for 15-20 minutes.
- Call a poison control center or doctor for treatment advice.

If inhaled:
- Move person to fresh air.
- If person is not breathing, call 911 or an ambulance, then give artificial respiration, preferably mouth-to-mouth if possible.
- Call a poison control center or doctor for further treatment advice.

If in eyes:
- Hold eye open and rinse slowly and gently with water for 15-20 minutes.
- Remove contact lenses, if present, after the first 5 minutes, then continue rinsing eye.
- Call a poison control center or doctor for treatment advice.

Other: Have the product container or label with you when calling a poison control center or doctor or going for treatment.
Note to Physician: Contains petroleum distillate – vomiting may cause aspiration pneumonia.

ENVIRONMENTAL HAZARDS

This material is toxic to fish. Do not apply directly to water by cleaning of equipment or disposal of wastes. Do not allow chips and dust generated during paint removal to enter water. Dispose of paint debris in an approved landfill. Do not discharge effluent containing this product into lakes, streams, ponds, estuaries, oceans or other waters unless in accordance with the requirements of a National Pollutant Discharge Elimination System (NPDES) permit and the permittiqg authority has been notified in writing prior to discharge. Do not discharge effluent to sewer systems without previously notifying the local sewage treatment plant authority. For guidance contact your State Water Board or Regional Office of the EPA.

PHYSICAL OR CHEMICAL HAZARD

Do not use or store near heat or open flame.

STORAGE AND DISPOSAL

Do not contaminate water, food or feed by storage or disposal. Open dumping is prohibited.
PESTICIDE DISPOSAL: Pesticide wastes are acutely hazardous. Improper disposal of excess pesticide, spray mixture, or rinsate is a violation of Federal Law. If these wastes cannot be disposed of by use according to label instructions, contact your State Pesticide or Environmental Control Agency, or the Hazardous Waste representative at the nearest EPA Regional Office for guidance.
CONTAINER DISPOSAL: Non-refillable container. Do not reuse or refill this container. Triple rinse as follows: Empty the remaining contents into application equipment or a mix tank and drain for 10 seconds after the flow begins to drip. Fill the container 1/4 full with water and recap. Shake for 10 seconds. Pour rinsate into application equipment or a mix tank or store rinsate for later use or disposal. Drain for 10 seconds after the flow begins to drip. Repeat this procedure two more times.

FOR CHEMICAL EMERGENCY, SPILL, LEAK, EXPOSURE OR ACCIDENT, CALL TOLL FREE: **CHEMTREC 1-800-424-9300** (DAY OR NIGHT) MEDICAL ADVISORY: CONTACT YOUR LOCAL POISON CONTROL CENTER OR CALL **1-800-854-6813.**

0 81948 10049 6